

PROJECT REFERENCE DATA SHEETS

Project Name ▶ Various Transit Projects

Client/Owner ▶ Transit Client **Yr.** ▶ --

Design Cost ▶ -- **Contract Cost** ▶ --

Description of Work:

CSE has performed many structural reviews for transit projects. The scopes of these projects typically include a detailed field condition survey, condition survey report, repair alternative evaluation, pre-design report, repair designs and the preparation of the 90% design and 100% design contracts.

We have also performed safety surveys, shoring design, repair alternative evaluations and preparation of the pre-design report, structural rehabilitation design repairs and the preparation of the 60% Design, 90% Design, 100% Design and Tender ready contract specifications.

CSE performed a detailed structural building condition evaluation on two Carhouse Garage building facilities.

CSE has also completed a detailed field condition survey, repair alternative evaluation and preparation of the pre-design report for the service pits at a Bus Garage.

Other CSE work included the structural evaluation of the floor structures, the structural reinforcing of the existing floors and the design of heavy duty steel floors at the a transit Yard.

Figure/Photo

